

**TRAFFIC UPDATE: TOUR BUS ACCIDENT AT KM15.8 JALAN GENTING HIGHLANDS ON
30 MAY 2026**

An accident occurred at approximately 5pm today involving 2 buses and 1 SUV at KM 15.8 Jalan Genting Highlands (downhill). There were no casualties reported. Our emergency response teams was on site with local authorities to provide assistance to affected passengers as required.

The affected buses have been moved to a safe area (KM16 Jalan Genting Highlands) and clean-up procedures are underway. Both uphill and downhill roads are open to traffic and traffic flow is smooth.

Guests are advised to remain vigilant while traveling to and from the resort.

Lingkarank Cepak Sdn Bhd
30 May 2026